

HYUNDAI

ENGINE HOUSE INC

	<u>VIN</u>	<u>LITER/ CI</u>	<u>CYL</u>	<u>YEAR</u>	<u>DESCRIPTION</u>	<u>PRICE</u>	<u>CORE</u>
1	A,J	1.5/1468	4	88-94	Excel & Scoupe, 4G15, FWD, Non MCA Jet Head, FI, 8 Valve.	\$1,690.00	\$350.00
2	J	1.5/1468	4	85-87	Excel, G15B Or G4AJ, FWD, MCA Jet Head, Carbureted.	\$1,690.00	\$350.00
3		1.5/1495	4	9/99-00	Accent, G4EK, SOHC, 12 Valve, Hydraulic & Roller Rockers, Crank Sensor On Block, Cam Sensor On Head. No Motor Mount On Right Rear Of Block.	\$1,895.00	\$350.00
4		1.5/1495	4	8/94-9/99	Accent, G4EK, SOHC, 12 Valve, Hydraulic Lifters & Roller Rockers, Crank Sensor On Block, Cam Sensor On	\$1,895.00	\$350.00
5		1.5/1495	4	96-97	Accent, G4EK, DOHC, 16 Valve, Crank Sensor On Block, Cam Sensor On Head.	\$1,895.00	\$350.00
6		1.5/1495	4	4/94-95	Scoupe, G4EK, 12/94-4/94, SOHC, 12 Valve, Hydraulic Lifters & Roller Rockers, Crank Sensor On Flywheel, Cam Sensor On Distributor	\$1,850.00	\$350.00
7	N	1.5/1495	4	8/92-7/94	Scoupe, G4EK, SOHC, 12 Valve, Adjustable & Slider Rockers, Crank Sensor On Flywheel, Cam Sensor In Distributor.	\$1,825.00	\$350.00
8	Y,R	1.6/1595	4	92-95	Elantra, 4G61, G4DR, FWD, DOHC, 16 Valve.	\$1,995.00	\$350.00
9		1.6/1599	4	00-06	Accent, G4ED, DOHC, 16 Valve.	\$2,425.00	\$450.00
10		1.8/1795	4	96-99	Elantra 99-96, Tiburon 97, G4GM, DOHC, 16 valve, Non VVT, Crank Sensor Is On Exhaust Side At Rear Of Block, Cam Sensor Is Behind Cam Gear, Block #RD18, Head #7C.	\$2,095.00	\$350.00
11	M	1.8/1836	4	93-95	Elantra, 4G67, G4CN, FWD, DOHC, 16 Valve.	\$2,095.00	\$350.00
12		2.0/1975	4	03-06	Elantra 06-04, Tiburon 06-03, Tucson 06-04, G4GF, DOHC, 16 Valves, VVT	\$2,695.00	\$450.00
13	F	2.0/1975	4	97-03	Tiburon 01-97, Elantra 03-97, G4GF, DOHC, 16 Valve.	\$2,550.00	\$350.00
14		2.0/1997	4	96-98	Sonata, G4CP, DOHC, 16 Valve, 6 Bolt Flywheel, Non Turbo, Crank Sensor On Oil Pump, Cam Sensor On Front of Head (Intake Side).	\$2,175.00	\$350.00
15	R	2.0/1997	4	92-95	Sonata, 4G63, DOHC, 16 Valve, 6 Bolt Flywheel, Non Turbo.	\$2,175.00	\$350.00
16	L,S	2.4/2350	4	89-91	Sonata 91-89, G64B, FWD, SOHC, MCA Jet Head, 8 Valve, Big Oil Pump.	\$1,995.00	\$350.00
17		2.4/2351	4	99-06	Sonata 06-99, Santa Fe 06-01, 4G64, G4JS, DOHC, 16 Valve, Mitsubishi Engine Only For Hyundai, Right Side Intake Port, Intake Port Has Injector Hole, Aluminum Oil Pan, Belt Driven Cam.	\$2,425.00	\$350.00
18		2.5/2493	V6	99-01	Sonata, V6, G6BV, DOHC, 24 Valve .	\$2,795.00	\$350.00
19		2.7/2656	V6	00-06	Sonata 05-02, Santa Fe 06-00, Tucson 06-04, Tiburon 06 03, Aluminum Block, V6, G6BA, DOHC,24Valve.	\$2,895.00	\$500.00
20		3.0/2972	V6	1	XG300, G6CT, DOHC, 24 Valve.	\$2,695.00	\$500.00
21	T	3.0/2972	V6	97-98	Sonata, 6G72 & G6AT, SOHC, 12 Valve, FWD, Cam Sensor Mounts to Front of Right Head	\$2,195.00	\$425.00
22	T	3.0/2972	V6	89-96	Sonata, 6G72 & G6AT, SOHC, 12 Valve, FWD	\$2,150.00	\$425.00

* Prices are subject to change, Please call for sale prices and to verify prices listed.