

# ACURA ENGINE HOUSE INC

	VIN	LITER/ CI	CYL	YEAR	DESCRIPTION	PRICE	CORE
1		1.6/1590	4	88-89	Integra, D16A1, DOHC, 16 Valve, 2 Bolt Mount For TDC Sensor On Rear Of Exhaust Camshaft, 24mm Crank Snout	\$1,675.00	\$350.00
2		1.7/1670	4	92-93	Integra, B17A1, DOHC, 16 Valve	\$2,200.00	\$450.00
3		1.8/1834	4	96-01	Integra GSR, B18C1, DOHC, 16 Valve. Crank Angle Sensor, V-TEC	\$2,150.00	\$650.00
4		1.8/1834	4	97-01	Integra Type R, B18C5, DOHC, 16 Valve. Crank Angle Sensor, V-TEC	\$2,125.00	\$650.00
5		1.8/1834	4	96-01	Integra GS, LS & RS, B18B1, DOHC, 16 Valve. Crank Angle Sensor, Non V-TEC	\$2,100.00	\$500.00
6		1.8/1834	4	94-95	Integra GSR, B18C1, DOHC, 16 Valve, V-TEC	\$2,150.00	\$650.00
7		1.8/1834	4	94-95	Integra GS & LS, B18B1, DOHC, 16 Valve. Non V-TEC	\$2,125.00	\$350.00
8		1.8/1835	4	90-93	Integra, B18A1, DOHC, 16 Valve, Non V-TEC	\$2,125.00	\$350.00
9		2.0/1998	4	02-06	RSX, K20A3, DOHC, 16 Valve, V-TEC (Intake only) 160 hp	\$3,235.00	\$650.00
10		2.0/1998	4	02-05	RSX-S TYPE, K20A2, DOHC, 16 Valve, V-TEC (Intake & Exhaust) 200hp.	\$3,400.00	\$650.00
11		2.2/2156	4	97	CL 2.2L, F22B1, SOHC, 16 Valve, V-TEC. Crank Angle Sensor Mount To Oil Pump.	\$2,095.00	\$350.00
12		2.3/2253	4	98-99	CL 2.3L, F23A1, SOHC, 16 Valve, V-TEC	\$2,095.00	\$300.00
13		2.5/2451	5	95-98	2.5TL, G25A4, 5 Cylinder, 20 Valve, SOHC. Cam & Crank Angle Sensor	\$2,850.00	\$350.00
14		2.5/2451	5	91-94	Vigor, G25A1, SOHC, 20 Valve, Cam Sensor	\$2,850.00	\$350.00
15		2.7/2675	V6	87-90	Legend, C27A1, SOHC, 24 Valve, Without Oil Level Sensor Hole In Block.	\$2,375.00	\$350.00
16		2.7/2675	V6	87-90	Legend, Sterling, C27A1, SOHC, 24 Valve, Oil Level Sensor Hole In Block.	\$2,375.00	\$350.00
17		3.0/2997	V6	97-99	CL 3.0L, J30A1, SOHC, 24 Valve, V-TEC	\$2,525.00	\$375.00
18	V	3.2/3165	V6	12/95-97	SLX, 6VD1, SOHC, 24 Valve. Crank Angle Sensor Mounts To Front Of Block. Cam Angle Sensor Mounts To Left Front Of Head	\$2,295.00	\$350.00
19		3.2/3206	V6	95-98	3.2 TL, C32A6, SOHC, 24 Valve	\$2,675.00	\$350.00
20		3.2/3206	V6	93-95	2 Door Legend L, LS & 4 Door GS. C32A1, SOHC, 24 Valve, With Oil Cooler, Cam Angle Sensor Has Male Connector, Water Pump Has 2 Outlets For Oil Cooler	\$2,525.00	\$350.00
21		3.2/3206	V6	93-95	4 Door Legend, 4 Door L, LS & SE, C32A1, SOHC, 24 Valve, Without Oil Cooler, Cam Angle Sensor Has Male Connector, Water Pump Has 1 Outlet	\$2,525.00	\$350.00
22		3.2/3206	V6	91-92	92-91 Legend Coupe, 92-91 Sedan, C32A1, SOHC, 24 Valve, With Oil Cooler, Cam Angle Sensor Has Female Connector, Water Pump Has 2 Outlets For Oil Cooler	\$2,525.00	\$350.00
23		3.2/3210	V6	04-06	3.2 TL, J32A3, SOHC, 24 Valve, V-TEC	\$4,050.00	\$750.00
24		3.2/3210	V6	02-03	3.2 TL S-TYPE, 3.2 CL S-TYPE. J32A2, SOHC, 24 Valve, V-TEC	\$3,650.00	\$75.00
25		3.2/3210	V6	98-03	3.2 TL 03-99, 3.2 CL 03-01. J32A1, SOHC, 24 Valve, V-TEC	\$3,650.00	\$750.00
26		3.5/3471	V6	01-02	MDX, J35A3, SOHC, 24 Valve. V-TEC.	\$3,130.00	\$475.00
27		3.5/3473	V6	96-04	3.5RL, C35A1, SOHC, 24 Valve, Balance Shaft	\$3,560.00	\$800.00
28	X	3.5/3494	V6	98-99	SLX, 6VE1, DOHC, 24 Valve.	\$2,805.00	\$850.00

\* Prices are subject to change. Please call for sale prices and to verify prices listed.