

# MAZDA

# ENGINE HOUSE INC

	<u>VIN</u>	<u>LITER/CI</u>	<u>CYL</u>	<u>YEAR</u>	<u>DESCRIPTION</u>	<u>PRICE</u>	<u>CORE</u>
1		1.5/1489	4	10/97-6/98	Protégé. Z5 Engine, DOHC, 16 Valve. Both Cams Driven By Timing Belt	\$2,195.00	\$400.00
2		1.5/1489	4	7/97-7/95	Protégé. Z5 Engine, DOHC, 16 Valve. Intake Cam driven by Timing Belt With the Exhaust Cam Driven By A Chain Off The Intake Cam	\$2,195.00	\$400.00
3		1.6/1597	4	6/98-01	Protégé, ZM Engine, DOHC, 16 Valve. Crank Sensor On Oil Pump	\$2,375.00	\$450.00
4		1.6/1597	4	9/90-8/93	Miata, B6 Engine, DOHC, Hydraulic Lifter, 27mm Crank Snout, 16 Valve, From Chassis #NA35-209447.In '90 check Crank Snout & Chassis #	\$2,175.00	\$350.00
5		1.6/1597	4	5/89-9/90	Miata, B6 Engine, DOHC, 16 Valve, Hydraulic Lifters, 22mm Crank Snout, To Chassis #NA35-209446.	\$2,050.00	\$350.00
6		1.8/1839	4	7/00-05	Miata, BP Engine, DOHC, 16 Valve, FWD, 27mm Crank Snout, Variable Valve Timing, Adjustable ShimType Lifters, Cam And Crank Position Sensors.	\$2,550.00	\$450.00
7		1.8/1839	4	6/98-11/00	Protégé,FP Engine, DOHC, 16 Valve, Crank & Cam Sensor	\$2,450.00	\$475.00
8		1.8/1839	4	11/97-8/00	Miata, BP Engine, DOHC, 16 Valve, FWD, 27mm Crank Snout, Adjustable Shim Type Lifters, Cam And Crank Position Sensors.	\$2,450.00	\$450.00
9		1.8/1839	4	6/96-8/98	BP, Protégé, DOHC, 16 Valve, 27mm Crank Snout, Crank Position Sensor On Oil Pump. Valve AdjustingShim Type Buckets	\$2,425.00	\$400.00
10		1.8/1839	4	7/95-11/97	Miata, BP Engine, DOHC, 16 Valve, FWD, 27mm Crank Snout, Hydraulic Rockers, Crank Position Sensor On Oil Pump.	\$2,295.00	\$350.00
11		1.8/1839	4	4/94-7/96	BP, Protégé, DOHC, 16 Valve, 27mm Crank Snout, Crank Position Sensor On Oil Pump.	\$2,295.00	\$350.00
12		1.8/1839	4	8/93-7/95	Miata, BP Engine, DOHC, 16 Valve, FWD, 27mm Crank Snout, Hydraulic Rockers, No Crank PositionSensor On Oil Pump.	\$2,295.00	\$350.00
13		1.8/1839	4	2/91-7/94	Protégé, BP Engine, SOHC, 16 Valve, 27mm Crank Snout.	\$2,195.00	\$350.00
14		1.8/1839	4	2/91-4/94	Protege, BP Engine, DOHC, 16 Valve, 27mm Crank Snout, No Cam Or Crank Position Sensors	\$2,150.00	\$350.00
15	FSD	2.0/1991	4	8/97-03	626 & MX-6 02-8/97, Protégé 03-11/00, FS Engine, DOHC, 16 Valve, Adjustable Shim Type Lifter, Crank Angle Sensor Mounts To Oil Pump, Cam Sensor In Valve Cover	\$2,480.00	\$350.00
16	FSD	2.0/1991	4	6/95-8/97	626 & MX-6, FS Engine, Vin FSD for 626 / MX6, DOHC, 16 Valve. Crank Angle Sensor Mounts To Oil Pump.	\$2,495.00	\$350.00
17	FSD	2.0/1991	4	1/92-5/95	626 & MX-6, FS Engine, DOHC, 16 Valve. For 1995 models: Does Not Have Crank Angle Sensor.	\$2,450.00	\$350.00
18		2.2/2184	4	93-8/97	B2200. F2 Engine, SOHC, RWD, 8 Valve, EGR In Head	\$1,795.00	\$350.00
19		2.2/2184	4	4/87-92	626 LX/DX, MX-6, F2 Engine, 12 Valve, FWD,	\$1,750.00	\$350.00
20	2.3	2.3/2260	4	04-06	Mazda 3, Mazda 5, Mazda 6, Ford Dura-Tec 23, DOHC, 16 Valves, FWD, Water pump not included, Timing chain included but not installed.	\$2,895.00	\$550.00
21	2.3	2.3/2260	4	05-06	Tribute, Ford Dura-tec 2.3, DOHC, 16 Valve, Water pump not included, Timing chain included but not installed.	\$2,895.00	\$550.00

\* Prices are subject to change, Please call for sale prices and to verify prices listed.

22	D	2.3/140	4	04-05	B2300, RWD, DOHC, 16 Valve, Block # 1L5G-BA, Head # 1S7G-BT	\$2,790.00	\$650.00
23	D	2.3/140	4	02-03	B2300, RWD, DOHC, 16 Valve, Block # 4L5G-BA, Head # 1S7G-BT, BU Or BV, Engine Code 1G-270AB or 1G-271AB	\$2,695.00	\$650.00
24	D	2.3/140	4	01-02	B2300, RWD, DOHC, 16 Valve, Block #1L5G-BA, Head # 1S7G-BT, BU Or BV, Engine Code 1G-270AAOr 1G-271AA Only	\$2,695.00	\$650.00
25	A	2.3/140	4	95-97	B2300. Dual Spark Plugs, Block F57E-DC, Head #F57E-E11C	\$1,895.00	\$475.00
26	A	2.3/140	4	94	B2300, OHC, FI, Dual Spark Plugs, Head #E97E-BA/E89E-AB	\$195.00	\$475.00
27	C	2.5/153	4	98-01	B2500, RWD, OHC, 8 Spark Plug, Block #F77E-AA, Head #F57E-E11C	\$1,895.00	\$475.00
28		2.6/2606	4	9/89-9/93	B2600 2WD Only, G6 Engine, 12 Valve, Balance Shaft, Hydraulic Lifters.	\$2,350.00	\$500.00
29		2.6/2606	4	11/88-9/93	B2600 4WD Only, G6 Engine, 12 Valve, Balance Shaft, Hydraulic Lifters	\$2,350.00	\$500.00
30		2.5/2493	V6	8/97-02	Millenia, KL Engine, DOHC, 24 Valve, Aluminum Block, Oval Intake Ports, No Cam Sensor, No OilCooler	\$2,895.00	\$450.00
31		2.5/2493	V6	8/97-02	626, KL Engine, DOHC, 24 Valve, Aluminum Block, Oval Intake Ports, Cam Sensor On Right Front OfHead, Crank Trigger	\$2,895.00	\$450.00
32	D	2.5/2493	V6	1/92-8/97	626 8/97-1/92, MX-6 7/97-12/92,Millenia 8/95-1/95, KL Engine, DOHC, 24 Valve, Aluminum Block, OvalIntake Ports, No Cam Sensor	\$2,575.00	\$450.00
33		2.5/2493	V6	11/93-1/95	KL Engine, Millennia Only. DOHC, 24 Valve, Aluminum Block, Square Intake Ports	\$2,575.00	\$450.00
34	G	2.5/153	V6	01-02	MPV. V6, DURATEC, DOHC, Block #XU3E-6015-BA, 8MM Knock Sensor Hole. Head #F73E/YS2E, Crank #F53E-6303-AB/BA	\$2,390.00	\$450.00
35	G	2.5/153	V6	00	MPV. V6, DURATEC, DOHC, Block #XU3E-6015-AB/BA, 12MM Knock Sensor Hole. Head#F73E/YS2E, Crank #F53E-6303-AB/BA	\$2,390.00	\$450.00
36	G	2.5/153	V6	99	MPV. V6, DURATEC, DOHC, Block #XU3E-6015-AB/BA, 12MM Knock Sensor Hole. Head#F73E/YS2E, Crank #F53E-6303-AB/BA	\$2,390.00	\$450.00
37		3.0/2954	V6	03-05	Mazda 6, Ford Dura-Tec, DOHC, 24 Valves	\$2,295.00	\$475.00
38		3.0/2954	V6	9/95-5/99	MPV 98-9/95, JE Engine, SOHC, 18 Valve, Oil Pump Mounts To Front, Crank Position Sensor MountsTo Oil Pump	\$2,495.00	\$475.00
39		3.0/2954	V6	7/88-9/95	929 91-11/88, MPV 9/95-7/88, JE Engine, SOHC. If '88 Check Production Date	\$2,495.00	\$475.00
40		3.0/2954	V6	7/91-95	929, JE Engine, DOHC, 24 Valve	\$2,495.00	\$475.00
41	1	3.0/182	V6	01-04	2001 Tribute Engine Code 1G-754AA & AB, 2004-2002 ALL .V6, DOHC, 24 Valve. Crank # V86. CrankSensor, Cam Sensor, With Oil Cooler	\$2,350.00	\$500.00
42	1	3.0/182	V6	01-04	2001 Tribute Engine Code 1G-752AA & AB, 2004-2002 ALL .V6, DOHC, 24 Valve. Crank # V86. CrankSensor, Cam Sensor, No Oil Cooler	\$2,350.00	\$500.00
43		3.0/182	V6	02-03	MPV, DOHC. 24 Valve, Block # XW4E-BA, Head # RT. YF1E-6090-FC, LFT # Y48E-6C064-BB	\$2,495.00	\$500.00
44	U	3.0/183	V6	02-04	B3000, RWD, Roller Cam, OHV, Block #2L1E, Head #F6DE-GC.	\$1,775.00	\$475.00
45	U	3.0/183	V6	99-01	B3000, RWD, Roller Cam, OHV, Block #XF1E, Head #F6DE	\$1,625.00	\$450.00

\* Prices are subject to change, Please call for sale prices and to verify prices listed.

46	U	3.0/183	V6	95-98	B3000, RWD, Roller Cam, Block #F58E, F6AE, Head #E6AE, Crank #E58E, F5DE, Crank Has 5 Counter Weights	\$1,595.00	\$350.00
47	U	3.0/183	V6	94	B3000, RWD, Roller Cam, Block #F2DE-BA	\$1,595.00	\$350.00
48	E	4.0/244	V6	02-03	B4000, SOHC, Block # BLOCK # 1L2E, HEAD # 1L2E, CRANK # XL2E , 8 Bolt Flywheel	\$2,685.00	\$450.00
49	E	4.0/244	V6	1	B4000. SOHC, Block # 97JM-AE, Head # 97JM-CD, Crank # 97JM-AC, 8 Bolt Flywheel	\$2,685.00	\$450.00
50	X	4.0/244	V6	99-00	B4000, Block # 97TM-AB, Head # 98TM-AD, Crank #97TM-AA, 8 Bolt Flywheel	\$189.00	\$500.00
51	X	4.0/244	V6	98	B4000, With Or Without EGR, Block # 97TM-AB, Head # 98TM, Crank # 97TM-AA, 8 Bolt Flywheel	\$1,895.00	\$500.00
52	X	4.0/244	V6	97	B4000, With Or Without EGR, Block # 97TM-AB, Head # 96TM-AD, Crank # 97TM-AA, 8 BoltFlywheel	\$1,895.00	\$500.00
53	X	4.0/244	V6	95-96	B4000, With Or Without EGR, Block # 95TM, 96TM-AB, Head # 95TM,96TM	\$1,895.00	\$500.00
54	X	4.0/244	V6	94-91	B4000 94 , Navajo Manual Trans 92-91, Navajo Auto Or Manual Trans 94-93, Block # 90TM-AB, Head #90TM-BE.	\$1,850.00	\$500.00
55	X	4.0/244	V6	91-92	Navajo 92-91 Auto Trans Only, Block # 90TM-AB, Head #90TM-BE	\$1,850.00	\$500.00

\* Prices are subject to change, Please call for sale prices and to verify prices listed.